



## Tech Note

From Comfort Controls

Date: 2007-04-27

### Clamping band on FJVR



New FJVR with clamping band



Old FJVR

We had complaints that old FJVR was breaking by the flaps were you tighten the screw. New FJVR is with clamping band so there are no breakable parts on the socket.

All FJVR elements will have socket with clamping band. Following code numbers will be affected:

- 003L1040 FJVR 10-50°C
- 003L1045 FJVR 10-80°C (locked between setting 4 and 5)
- 003L1047 FJVR 10-50°C (FJVR in industrial pack)
- 003L1070 FJVR 10-80°C
- 003L1072 FJVR in chrome 10-50°C
- 003L1077 FJVR 10-80°C (FJVR in industrial pack)

## Delivery

We have old sockets on stock, new FJVR will be available when stock is emptied.

## Technical support

CD-E, Peter Kjeldsteen Christensen