


Instructions



Service kits



| A | PN | DN | Δp (bar) | | | | | | | Code No. |
|----|--------------|----|-----------------------------------|----------------|----------------|----------------|-----|-----|----------|----------|
| | | | $0.05 \div 0.5$ $0.1 \div 0.5$ | $0.2 \div 1.0$ | $0.3 \div 2.0$ | $0.8 \div 1.6$ | 0.2 | 0.3 | 0.5 | |
| 16 | 15 \div 32 | | - | x | | - | x | - | - | 003H1330 |
| | | | - | - | | - | - | x | - | 003H1326 |
| | | | - | - | | - | - | - | x | 003H1331 |
| | | | - | - | | x | - | - | - | 003H1332 |
| 25 | 15 \div 50 | | - | - | | x | | - | 88835920 | |
| | 15 \div 25 | | - | - | | - | | x | 88835930 | |
| | 32 \div 50 | | - | - | | - | | x | 88835940 | |

| | |
|----|-----------------------------|
| M1 | CuSn5ZnPb (Rg5) |
| M2 | EN-GJS-400-18-LT (GGG 40.3) |

| B | PN | DN | Δp_b (bar) | | | | | | | Code No. |
|----|--------------|----|--------------------|----------------|----------------|----------------|-----|-----|-----|----------|
| | | | $0.1 \div 0.5$ | $0.2 \div 1.0$ | $0.3 \div 2.0$ | $0.8 \div 1.6$ | 0.2 | 0.3 | 0.5 | |
| 16 | 15 \div 32 | | | | | | x | | | 003H1330 |
| | | | | | | | x | | | 88835920 |
| 25 | 32 \div 50 | | | | | | | | | - |
| | | | | | | | | | | |



| | | | |
|---|-------|--|----|
| 2 | PN 16 | AVP, AVP-F, AVPB, AVPB-F, AVD, AVQ, AVQM | M1 |
| 2 | PN 16 | AVPQ, AVPQ-F | M1 |
| 3 | PN 16 | AVPQ 4, AVPQ 4-F | M1 |
| 3 | PN 16 | AVPA | M1 |

