

Tech. Note.

New dismounting union nut to replace the old, for all the RA 2000 valves.

Date: 2004.08.18

The dismounting union nut known under the code number 003L0213 has got a new look. The change has been made for the dismounting union nut to fit the FHV-R valve. You will receive the new one, when the old element is no longer at storage. There are 100 pcs. at storage.



Old dismounting union nut.



New dismounting union nut.

Packaging

No changes in the packaging have been made.

Orders

Danfoss Silkeborg

Technical support

Peter Kjeldsteen Christensen CD-ST