



Tech Note

from Residential & Commercial Comfort Controls
2004.04.02

Modifications to the FJVR sensor

The FJVR Return Temperature Limiter sensor (code no. 003L1040 and 003L1070) is being modified/improved.

As from April 14th 2004 the slotted screw at the sensor connection will be replaced by an internal hexagonal for standard 4 mm Allen key.



Technical inquiries to Michael Nielsen in Marketing, Danfoss Silkeborg.